



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

RBW6522A00231-W142AJ-

3T-2

Job Sheet 199140



Part No: RBW6522A00231-W142AJ-3T-2 **Job Qty:** 1 pcs

Part Name: Base Plate Assembly



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 8/13/19

Job Tracking No:

Created By: Marie Lajeunesse

Due Date: 10/7/19

Description:

Type: SOLD

Note: DWG RBW6522A00231-W142AJ-3T Rev 5 IPP Rev A 18.02.13 New issue DP Verify DD

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
100	Small Fab - 1	1 pcs	10/7/19		0.00	0.10	Small Fab - 1		
							Small Fab - 2		
							Small Fab - 3		
							Small Fab - 4		
							Small Fab - 5		
							Small Fab - 6		
							Small Fab - 7		
							Small Fab - 8		
120	SL-2500Y - 2 - B4B	1 pcs	10/7/19		1.00	0.50	SL-2500Y -1 - B4B		
120	QC 2	1 pcs	10/7/19		0.00	0.00	QC 2 - 1		
							QC 2 - 12		
							QC 2 - 14		
							QC 2 - 17		
							QC 2 - 19		
							QC 2 - 2		
							QC 2 - 20		
							QC 2 - 22		
							QC 2 - 23		
							QC 2 - 25		
							QC 2 - 32		
							QC 2 - 33		
							QC 2 - 35		
							QC 2 - 39		
							QC 2 - 4		
							QC 2 - 40		
							QC 2 - 44		
							QC 2 - 45		
							QC 2 - 48		
							QC 2 - 49		
							QC 2 - 50		
							QC 2 - 51		



Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Container No: S225942



Part: RBW6522A00231-W142AJ-3T-2

Job No: 199140

Serial No/Batch: S225942

Revision: 5

Inspector:

Exp Date:

Instructions:

Date: 10/24/19

Plex 8/13/19 1:13 PM Dart.lajeunesse.marie

				QC 2 - 52	
				QC 2 - 57	
				QC 2 - 62	
				QC 2 - 63	
				QC 2 - 8	
				QC 2 - 66	
				QC 2 - 64	
				QC 2 - 65	
				QC 2 - 5	
				QC 2 - 71	
				QC 2 - 73	
				QC 2 - 69	
140	QC 8	1 pcs	10/7/19	0.00 0.00	QC 8 - 12
					QC 8 - 14
					QC 8 - 17
					QC 8 - 20
					QC 8 - 25
					QC 8 - 3
					QC 8 - 32
					QC 8 - 33
					QC 8 - 35
					QC 8 - 39
					QC 8 - 4
					QC 8 - 44
					QC 8 - 45
					QC 8 - 49
					QC 8 - 58
					QC 8 - 8
					QC 8 - 9
					QC 8 - 68
					QC 8 - 67
					QC 8 - 1 (A)
					QC 8 - 47
					QC 8 - 40
					QC 8 - 52
					QC 8 - 23
					QC 8 - 57
150	Packaging 3-1 - Stock - B4B	1 pcs	10/7/19	0.00 0.00	Packaging 3 - 1 - B4B
					Packaging 3 - 2 - B4B
					Packaging 3 - 3 - B4B
					Packaging 3 - 4 - B4B
					Packaging 3 - 5 - B4B
					Packaging 3 - 6 - B4B
					Packaging 3 - 7 - B4B
					Packaging 3 - 8 - B4B
					Packaging 3 - 9 - B4B
					Packaging 3 - 10 - B4B
					Packaging 3 - 11 - B4B
					Packaging 3 - 12 - B4B
					Packaging 3 - 13 - B4B
					Packaging 3 - 14 - B4B
					Packaging 3 - 15 - B4B
					Packaging 3 - 16 - B4B
					Packaging 3 - 17 - B4B
					Packaging 3 - 18 - B4B
					Packaging 3 - 19 - B4B
					Packaging 3 - 20 - B4B
					Packaging 3 - 21 - B4B
					Packaging 3 - 22 - B4B

DAS
28
9-89

				Packaging 3 - 23 - B4B	
				Packaging 3 - 24 - B4B	
				Packaging 3 - 25 - B4B	
				Packaging 3 - 26 - B4B	
				Packaging 3 - 27 - B4B	
				Packaging 3 - 28 - B4B	
				Packaging 3 - 29 - B4B	
				Packaging 3 - 30 - B4B	
				Packaging 3 - 31 - B4B	
				Packaging 3 - 32 - B4B	
				Packaging 3 - 33 - B4B	
				Packaging 3 - 34 - B4B	
				Packaging 3 - 35 - B4B	
				Packaging 3 - 36 - B4B	
160	QC 21 - SA	1 pcs	10/7/19	0.00 0.00	QC 21 - SA - 21
					QC 21 - SA - 70
					QC 21 - SA - 53

Part Op 100 - (Small Fab) 1-Assemble -7 onto -3 as per DWG sheet 3 note 1.
 Descriptions: 120 - (MORI SL2500Y LATHE) 1-Machine -7 to final dimensions as shown using -3 as template see note 1 sheet 3.
 130 - (QC2- Inspect parts off machine FAI/FAIB)
 140 - (QC8- Inspect parts - second check)
 150 - (Identify as per dwg & Stock Location: _____)
 160 - (QC21- Final Inspection - Work Order Release)

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
RBW6522A00231-W142AJ-3T-3	Base Plate	1 pcs (1 ea)	100-Small Fab - 1	5216024
RBW6522A00231-W142AJ-3T-7	Pad	1 pcs (1 ea)	100-Small Fab - 1	5216389

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
100-Small Fab - 1	RBW6522A00231-W142AJ-3T-3	1	0	0
	RBW6522A00231-W142AJ-3T-7	1	0	0

Part Specifications



Specifications could not be found.

Plex 8/13/19 1:13 PM Dart.lajeunesse.marie

This drawing, specifications, and concepts contained here in are the sole property of Dart Aerospace and may not be reproduced or used in any fashion without the prior written permission of Dart Aerospace Eugene, OR.

REVISIONS

REV	ECR	DESCRIPTION	DATE	INITIAL	APPROVED
3	15-0336	-2 ADDED ASSEMBLY FOR FINAL MACHINING OF -7, ADDED NOTE -7.	10/14/2015	RJC	JAG
4	16-0250	-2 CHD DIM WAS Ø4.402 IS Ø4.360; ADDED DIM .395.	12/5/2016	SM	JAG



NOTE:

△ ASSEMBLE -7 ONTO -3. MACHINE -7 TO FINAL DIMENSIONS AS SHOWN USING -3 AS TEMPLATE.



TITLE	TGB/SERVO ACTUATOR OIL SEAL FIT/EXTRACTION TOOL
DWG NO.	RBW6522A00231-W142AJ-3T-2
REV	5
MAT'L	UNLESS OTHERWISE SPECIFIED
HEAT TREAT	DIMENSIONS ARE IN INCHES
FINISH	.XXX ± .005 FRACTIONS ± 1/8
SPEC	.XX ± .01 ANGLES ± .5°
DRAWN BY:	.X ± .1 SURFACES = 125/
CHECKED:	1. BREAK ALL SHARP EDGES
OPPS APPR:	.015 x 45° OR .015R
QA APPR:	2. DIMENSIONAL LIMITS APPLY AFTER PLATING
APPROVED:	3. INTERPRET DIM AND TOL PER ASME Y14.36-2009
SCALE	1:2
DATE	10/14/2015
APPROVED:	USED ON MODEL
AW139	
SHEET 3 OF 10	

BASE PLATE ASSEMBLY

Entered: _____ Date: _____

WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐



Job: _____ Part No.: _____		DISPOSITION Rework ☐ ☐ ☐ Scrap ☐ ☐ ☐ Use-as-is ☐ ☐ ☐		DEPARTMENT/PROCESS Skid-tube ☐ ☐ ☐ ☐ ☐ Machining ☐ ☐ ☐ ☐ ☐ Large Fab ☐ ☐ ☐ ☐ ☐		Cross tube ☐ ☐ ☐ ☐ ☐ Small Fab ☐ ☐ ☐ ☐ ☐ Finishing ☐ ☐ ☐ ☐ ☐		Eng. (Non-AW) ☐ ☐ ☐ ☐ ☐ Prod. Eng. Coord. ☐ ☐ ☐ ☐ ☐ Rec/Store/Packaging ☐ ☐ ☐ ☐ ☐		Engineering ☐ ☐ ☐ ☐ ☐ Water Jet ☐ ☐ ☐ ☐ ☐ Supplier ☐ ☐ ☐ ☐ ☐ Quality ☐ ☐ ☐ ☐ ☐	
Date : _____		Sequence #: _____		QTY Affected : _____		MRB (QS1042)					
Description Work Order Deviation				Disposition							
Root Cause Operator ☐ ☐ ☐ ☐ ☐ Manufacturing Process ☐ ☐ ☐ ☐ ☐ Equip/Tooling ☐ ☐ ☐ ☐ ☐ Handling/Preservation ☐ ☐ ☐ ☐ ☐ Material ☐ ☐ ☐ ☐ ☐ Product Improvement ☐ ☐ ☐ ☐ ☐ Process Improvement ☐ ☐ ☐ ☐ ☐ Human Factors ☐ ☐ ☐ ☐ ☐				FAULT CATEGORY							
				Contamination ☐ ☐ ☐ ☐ ☐ Misaligned/off center ☐ ☐ ☐ ☐ ☐ BOM/Route ☐ ☐ ☐ ☐ ☐ Broken/Damage/Defect ☐ ☐ ☐ ☐ ☐ Incomplete/Unclear Instructions ☐ ☐ ☐ ☐ ☐ Drill Holes ☐ ☐ ☐ ☐ ☐ Fit/Function ☐ ☐ ☐ ☐ ☐							
				Pressure/Forced ☐ ☐ ☐ ☐ ☐ Bending ☐ ☐ ☐ ☐ ☐ Crushing ☐ ☐ ☐ ☐ ☐ Cracks ☐ ☐ ☐ ☐ ☐ Crimp/Kink/Ripple/Wave/Twist ☐ ☐ ☐ ☐ ☐ Marks/Chatter ☐ ☐ ☐ ☐ ☐ Mislabeled ☐ ☐ ☐ ☐ ☐							
Other/Details: _____				Power Loss/Surge ☐ ☐ ☐ ☐ ☐ Folio/Program ☐ ☐ ☐ ☐ ☐ Grain Direction ☐ ☐ ☐ ☐ ☐ Weld ☐ ☐ ☐ ☐ ☐ Wrong Stock Pulled ☐ ☐ ☐ ☐ ☐ Out of Sequence ☐ ☐ ☐ ☐ ☐ Off-set/Set-up ☐ ☐ ☐ ☐ ☐							
				Positioned Wrong ☐ ☐ ☐ ☐ ☐ Outside Tolerance ☐ ☐ ☐ ☐ ☐ Drawing ☐ ☐ ☐ ☐ ☐ Finish ☐ ☐ ☐ ☐ ☐ Part Lost/Missing ☐ ☐ ☐ ☐ ☐ Misread ☐ ☐ ☐ ☐ ☐							
				Completed By _____							
				Lead hand / Supervisor _____							
				QC / QA Coordinator _____							